

**THE NATIONAL CREDIT REGULATOR
SEPTEMBER 2025**

**DESCRIPTION- APPOINTMENT OF A SERVICE
PROVIDER TO REPAIR ONE ENERGIZER**

**CLOSING DATE: 03 SEPTEMBER 2025 AT 12H00 SHARP
CAT**

EMAIL YOUR SUBMISSION TO: SMinnaar@ncr.org.za

Terms of reference for the appointment of a service provider to repair one energizer.

1. Purpose

The NCR would like to appoint a service provider to repair one energizer at 232 -15th Road, Randjespark, Midrand.

2. Scope of work

The required work is listed below:

- 2.1 Supply Merlin Stealth M28 Main PC board
- 2.2 Replace the PC board
- 2.3 Re-install energizer and test

3. Pre- requisites

- 3.1 The bidder must be registered on the Central Supplier Database (CSD). Proof of registration must be provided.
- 3.2 The service provider must be registered with the Private Security Industry Regulatory Authority (PSIRA). Proof must be submitted.

4. Pricing schedule

Item	Description	Quantity	Unit Price	Price excluding VAT
1	Supply Merlin Stealth M28 Main PC board	1		
2	Replace the PC board	1		
3	Re-install energizer and test	1		
4	Travel cost	km		
Subtotal				
VAT@15%				
TOTAL				

Fraud / Anti-Corruption Hotline

Report any incidents of wrongdoing
to the KPMG Ethics Line

0800 20 53 17 (Toll Free)